

***Dominion
North Anna Power Station
Restart Readiness***

October 21, 2011 Briefing

***David A. Heacock,
President & Chief Nuclear Officer***

***Eugene S. Grecheck,
Vice President, Nuclear Development***


Dominion Assessment

Consistent With Part 100, Appendix A:


- No Functional Damage to Safety SSCs
- No Undue Risk to Health and Safety
- Restart Readiness Demonstrated

Event Perspective & Margins

Response Spectra Comparisons



Response Spectra Comparisons




Response Spectra Considerations

- Seismic Acceleration Response Spectra
 - Used To Conservatively Design Plants
 - Poor Indicators of Plant Damage
 - Does Not Account for Duration
- Cumulative Absolute Velocity (CAV) takes Duration and Acceleration into Account
 - Best Single Indicator of Energy Imparted
 - Best Single Indicator of Damage


Acceleration Time Histories

(very short, strong motion)





Containment Basemat (elevation 216')

Time Histories With DBE Superimposed



Conservatism In Modeling Structures


Horizontal Response Spectra vs. DBE @ Basemat & Elevation 291'



CAV Comparisons

Seismic Case	CAV North – South Direction (g-sec)	CAV East – West Direction (g-sec)	CAV Vertical Direction (g-sec)
August 23, 2011 Seismic Event (data from containment basemat)	0.172	0.125	0.110
Design Base Earthquake (rock-founded; synthetic time-history used for containment structure)	0.588	0.580	0.400
IPEEE Review Earthquake (rock-founded; synthetic time-history used for containment structure)	1.230	1.312	0.875
OBE exceedance criterion is CAV > 0.16 g-sec (EPRI TR – 100082 & RG 1.166)			

CAV Comparisons



Significant Design Margins

- Conservatism In Analytical Methods
- Conservatism in ASME Code
- Accident Load of Greater Capacity
- Seismic Test Standards

Seismic Margin Evaluated

- Safe Shutdown Components Previously Evaluated Capable in Excess of DBE
- GL 88-20 (IPEEE) & GL 87-02 (A46) results:
 - Inspected ~ 1800 Safe Shutdown Components
 - IPEEE evaluated to withstand $\geq 0.3g$
 - Exceptions (~ 50) capable to $\geq 0.16g$

The Plant Tells the Story

Unit 2 Turbine Building

Non-Safety
Related
Powdex
Demineralizer
Tanks



U2 Turbine Building

Powdex
Demineralizer
Tanks Base
Pedestal



Turbine Building Hallway

Crack In
Unreinforced
Non–Safety
Related
Block
Wall



Unit 1 Containment



Surface Crack In Interior Containment Wall

Dry Cask Storage




TN-32 Cask Movement



Application of Regulatory Guidance


10 CFR 100, Appendix A

“Prior to resuming operations, the licensee will be required to demonstrate to the Commission that no functional damage has occurred to those features necessary for continued operation without undue risk to the health and safety of the public.”




Regulatory Guidance

Station restart readiness assessment actions based on NRC endorsed guidance




RG 1.166, *Pre-earthquake Planning and Immediate Nuclear Power Plant Operator Post-earthquake Actions*, March 1997



RG 1.167, *Restart of a Nuclear Power Plant Shut Down by a Seismic Event*, March 1997

Regulatory Guidance



EPRI NP-6695,
*Guidelines for
Nuclear Plant
Response to an
Earthquake,*
December 1989

EPRI NP 6695 Guidance

Definition of Functional Damage:

“Significant damage to plant systems, components, and structures, either physical or other, which impairs the operability or reliability of the damaged item to perform its intended function. Minor damage such as slight or hairline cracking of concrete elements in structures does not constitute functional damage.”


EPRI NP 6695 Guidance

Recommended actions ... are based on the following concepts:

“The plant itself, not damage information from nearby communities or recorded distant ground motion, is the best indicator of the severity of the earthquake at the plant site.”

EPRI NP-6695 Figure 3-1


Short-Term Actions



EPRI NP-6695 Figure 3.2

Flow Diagram of Post-Shutdown Inspections and Tests

EPRI Damage Intensity of 0



Expanded Inspections

- Structural Component Inspections
- Inspections of Low HCLPF Items
- Electrical Inspections
- Hidden Damage Considerations
- Reservoir & Main Dam Inspections
- System Inspections
- Surveillance & Functional Testing
- Fuel & Vessel Internals Inspections
- ISFSI Pads and Casks

Demonstration Plan

- Conservatively Inspected Beyond EPRI Damage Intensity “0” Classification
- Assessments & Evaluations for NRC
 - Requests for Additional Information (~ 130)
 - Onsite Inspections
 - Augmented Inspection Team
 - Restart Readiness Inspection Team
- Root Cause Evaluation of Reactor Trip

Demonstration Plan

Restart Readiness Assessment:

- ✓ Completion of Demonstration Plan
- ✓ Review and Disposition of Open CRs Associated with Earthquake
- ✓ FSRC Review/Approval of Evaluations Demonstrating SSC Operability, Functionality, and Restart Readiness

What We Inspected/Tested

Inspection Effort

Dominion Effort Expended:

• Coordination	2376 hrs
• Walk down teams	4320 hrs
• Civil inspections	3552 hrs
• Electricians	1440 hrs
• I&C Technicians	<u>192 hrs</u>
Total (as of Oct 9 th)	~ 11880 hrs

Extensive Contractor Resources

Multiple External Consultants

Chemical Addition Tank

HCLPF value
= 0.19
No seismic
damage
identified



Boric Acid Storage Tank



HCLPF value
= 0.21
No seismic
damage
identified

Circulating Water Discharge



Unit 2 Tunnel Inspection


Pump In-service Test & Verification



Pump verification included assessing:

- Motor current
- Pump / motor vibration
- Pump flow
- Pump discharge pressure
- Oil analysis
- Bearing temps

Snubber Testing



Visual Inspections:

- 326 small bore Unit 1
- 362 small bore Unit 2
- 12 large bore per unit

Unit 1 Functional Testing:


- 4 tested due to visual – satisfactory
- 12 additional small bore
- 2 large bore



Unit 2 Functional Testing:

- 5 tested due to visual – satisfactory
- 61 small bore for outage
- 2 large bore for outage

Fuel Inspections



Visual inspection of RCCA hubs

Unit 2 Refueling:

Visually inspected

- 35 fuel assemblies
- 20 most seismic susceptible

RCCA drag load testing

- 48 fuel assemblies with rods from Cycle 21
- 48 assemblies with rods for Cycle 22

Fuel Inspections



Examining the underside of
a mid-span mixing grid

New Fuel Storage Area:

Visually inspected

- 18 new fuel assemblies
- 12 burnable poison assemblies

Verified self seating of

- 11 burnable poison assemblies

Measured RCCA insertion force


- 7 new fuel assemblies

Spent Fuel Pool:

Visually inspected

- 5 new fuel assemblies
- 5 burnable poison assemblies
- 10 irradiated fuel assemblies

Buried Piping



~ 100 ft of safety related buried pipe visually inspected
with wall thickness verified by UT

Buried Piping



~ 50 feet of Fire Protection piping visually inspected

Steam Generator Examinations

- Unit 1 - A S/G and Unit 2 - A & C S/Gs
 - Inspected ~3300 tubes per S/G
 - Video examined channel heads
- Structural & material condition of secondary
 - Steam Drum, Feeding, & J tubes
 - Upper support plates
- No evidence of degradation due to event

NDE Inspections & Testing on Welds

Outage scheduled weld inspections

- 34 PTs conducted
- 22 PT/UTs conducted
- 38 UTs conducted
- 14 VTs conducted

Post-earthquake weld inspections

- 14 PTs at expected high stress locations
- 2 UTs of previously identified welds with embedded flaws

No seismic damage identified

Inspection Results

- ✓ 134 System inspections completed
- ✓ 141 Structure inspections completed
- ✓ 46 Low HCLPF inspections completed
- ✓ ~ 445 Surveillance Tests/unit through Mode 5
 - ~ 29 tests/unit after exceeding Mode 4

Inspections Confirm EPRI Damage Intensity of “0”

Going Forward

Short-Term Actions



- ✓ Installed Temporary Free Field Seismic Monitor
- ✓ Installed Qualified UPS to Seismic Monitoring Panel in MCR
- ✓ Revised Abnormal Procedure 0-AP-36
 - Complete Start-Up Surveillances



Long-Term Actions

- Install permanent free-field seismic monitoring instrumentation
- Re-evaluate safe shutdown equipment identified in IPEEE review with HCLPF capacity $< 0.3g$
- Commit to RG 1.166 and 1.167

Long-Term Actions

- Perform seismic analysis of recorded event consistent with EPRI NP-6695
 - Develop floor response spectra at various building levels based on recorded input motion
 - Assess new floor spectra for exceedances with design base floor spectra
 - Evaluate selected equipment based on exceedances identified with new floor spectra

Long-Term Actions

- Revise UFSAR to document:
 - Recorded event
 - Seismic analysis of recorded event
 - Design controls on seismic margin
 - Commitment to RG 1.166 and 1.167
- Perform seismic evaluation for NRC GI-199

Summary

- OBE and DBE acceleration criteria were exceeded in certain directions and for certain frequencies by a very short duration earthquake
- CAV calculations indicate that no significant damage should be expected
- Effective strong motion duration indicates no damage should be expected
- Inspections confirm an EPRI Damage Intensity of “0”

Summary

- IPEEE and A46 evaluations demonstrate safe shutdown SSCs capable of peak accelerations in excess of DBE
- No safety related SSCs have required repair due to the earthquake
- Results of expanded inspections and tests have confirmed expectations

Conclusions

Part 100, Appendix A, Requirement Met

- ✓ No Functional Damage to Safety SSCs
- ✓ No Undue Risk to Health and Safety
- ✓ Restart Readiness Demonstrated

Acronyms

CAV - Cumulative Absolute Velocity

CR – Condition Report

DBE – Design Base Earthquake

EPRI – Electric Power Research Institute

FSRC – Facility Safety Review Committee

HCLPF – High Confidence of Low Probability of Failure

IPEEE – Individual Plant Examination of External Events

MCR – Main Control Room

PT – Penetrant Test

S/G – Steam Generator

SSC – Systems, Structures and Components

RCCA – Rod Cluster Control Assembly

RG – Regulatory Guide

UPS – Uninterruptible Power Supply

UT – Ultrasonic Test

VT – Visual Test