



[Top](#) > [Releases · Announcements](#) > [Press Releases](#) > [2013](#) > Disconnection of the Silt Fences at Fukushima Daiichi NPS

▶ Releases · Announcements

Press Releases

Archives

Announcements

Presentation & Handouts

Resource Gallery

Fuel Consumption / Fuel Purchases

Media Contacts

Press Releases Search

Press Releases 2013

Press Release (Apr 08,2013)

Disconnection of the Silt Fences at Fukushima Daiichi NPS

At around 10:10 today, April 8, a corporate company worker found disconnection of the silt fence at the Unit 5/6 intake canal, and the silt fence at the shallow draft quay which was tied up to prevent fish from moving out.

Since the wave height is currently too high for strong wind to work around the area, we will repair the silt fence after the weather has quiet down.

We will conduct additional sampling in front of the Unit 6 intake canal today.

There are no significant changes with the monitoring post data.

▲ Page Top

Measures towards the revitalization of Fukushima

About Compensation for Nuclear Damages
Current situation of Fukushima Daiichi and Daini nuclear power station

Measures towards reform

Business Streamlining
Nuclear Reform

Customer Communication

Service Guide
Online Service Request
Customer Support
FAQ
Customer Inquiries

Power Supply Facilities

Thermal
Hydroelectric
Nuclear
Renewable Energies
Power Supply & Network
Fuels

Corporate Information

Corporate Overview
Investor Relations
International Activities
Procurement
Overseas Consultancy Services
R&D

Contact Us

General Inquiries
Media Contacts
Investor Relations Inquiries
Procurement Inquiries
Customer Inquiries
Consultancy Inquiries