



Work at Fukushima nuclear plant

Photo taken on April 4, 2013, shows an area around a crack at the Fukushima Daiichi Nuclear Power Station in Fukushima Prefecture, from which highly radioactive water leaked into the sea in April 2011. The crack in front of the structure has been filled and covered with gravel. Installation work on a water shielding wall began at the plant on April 2, 2013. (Kyodo)

 [BUY PHOTOS >](#)

Related News

- 13:14 10 April
[SNAPSHOT: Decommission work at Fukushima plant](#) 