

< Reference >
September 17,2011
Tokyo Electric Power Company

Fukushima Daiichi Nuclear Power Plant Photo Collection

Date : September 15-16, 2011
Source : Tokyo Electric Power Company

List

<Unit 1>

- ① Reactor building cover from northern side
Sep 15, 2011
- ② Reactor building cover from northern side
Sep 15, 2011
- ③ View from large crane around a reactor building
Sep 15, 2011
- ④ Southern direction (Unit 3 & 4) from Unit 1
Sep 15, 2011

<Unit 2>

- ⑤ Overview of a reactor building from western hilltop
Sep 15, 2011

<Unit 3>

- ⑥ Overview of a reactor building from western hilltop
Sep 15, 2011
- ⑦ Rubble collection around southwest of a reactor building
Sep 16, 2011
- ⑧ Rubble collection preparation of a reactor building
~north direction (Unit 1&2) from Unit 3~
Sep 15, 2011

<Unit 4>

- ⑨ Overview of a reactor building from western hilltop
Sep 15, 2011
- ⑩ Rubble collection preparation of a reactor building
~north direction from Unit 4~
Sep 15, 2011

<Unit 5,6>

- ⑪ Overview of a reactor building from southwest side
Sep 15, 2011
- ⑫ Maintenance work at port and harbors from Unit 6
seaside yard
Sep 15, 2011

<Tank area>

- ⑬ RO concentrated water storage tank (H 1 east area)
Sep 15, 2011
- ⑭ RO concentrated water storage tank (H 1 area)
Sep 15, 2011

<Centralized Radiation Waste Treatment Facility>

- ⑮⑯ Overview
Sep 16, 2011

* All photos by TEPCO employee

Unit 1

①



① Reactor building cover from northern side
Sep 15, 2011

②



② Reactor building cover from northern side
Sep 15, 2011

③



③ View from large crane around a reactor building
Sep 15, 2011

④



④ Southern direction (Unit 3 & 4) from Unit 1
Sep 15, 2011

Unit 2

⑤



⑤ Overview of a reactor building from western hilltop
Sep 15, 2011



⑥

⑥ Overview of a reactor building from western hilltop
Sep 15, 2011



⑦

⑦ Rubble collection around southwest of a reactor building
Sep 16, 2011



⑧

⑧ Rubble collection preparation of a reactor building
~north direction (Unit 1&2) from Unit 3~
Sep 15, 2011

⑨



⑨ Overview of a reactor building from western hilltop
Sep 15, 2011

⑩



⑩ Rubble collection preparation of a reactor building
~north direction from Unit 4~
Sep 15, 2011

⑪



⑪ Overview of a reactor building from southwest side
Sep 15, 2011

⑫



⑫ Maintenance work at port and harbors from
Unit 6 seaside yard Sep 15, 2011

Tank area

⑬



⑬ RO concentrated water storage tank (H1 east area)
Sep 15, 2011

⑭



⑭ RO concentrated water storage tank (H1 area)
Sep 15, 2011

Centralized Radiation Waste Treatment Facility

⑮



⑯



⑮⑯ Overview
Sep 16, 2011

Location Map of Fukushima Daiichi Nuclear Power Plant

